

thermOweld® One Step Pole Plate:


High Quality Materials for the Electric, Utility, Telecom, Cathodic, and Rail Markets.

With the "One Step Pole Plate," grounding pole equipment is possible without the problems of having to drive a ground rod. Just place the plate in the hole with six inches of Contact GF back fill material below and above the copper plate. Then connect the wire to the pole above the ground line. This easy process is a quick and efficient way to get the job done.

This installation is equivalent to a ground rod driven into undisturbed soil.

Features

- No need to drive a ground rod when installed as directed.
- Reduces strain and injuries.
- Reduces installation time.
- Reduces grounding errors.
- 100% Copper plate with thermOweld® pigtail.
- Saves time and money.
- Used for grounding Class 5 and larger poles.
- Different configurations available to fit smaller diameter holes.



Catalog Number	Pigtail Size
38-5955-00	10 ft of #6 Solid
38-5955-03	10 ft of #4 Solid
38-5955-04	10 ft of #2 Stranded

